K C1 AND C2 OBSERVATIONS - INCLUDE RELEVANT SCHEDULE REFERENCES

Schedule ref.	Observations	Classification code

K CLASSIFICATION CODES

Meaning
C1 - danger present; immediate action is necessary. C2 - potentially dangerous; urgent action is necessary.

K C3 AND FI OBSERVATIONS - INCLUDE RELEVANT SCHEDULE REFERENCES

Schedule ref.	Observations	Classification code
7.17	Circuit identification requires improvement. View photo	C3

K CLASSIFICATION CODES

Meaning
C3 - improvement recommended. FI - further investigation is advised. These items do not affect the overall assessment.

P OBSERVATION PHOTOGRAPHS

Back to observation table

Observation 1 - C3



Observation

Circuit identification requires improvement.

Distribution board

1

Circuit

1

Inspection schedule

7.17 Condition of accessories including socket-outlets, switches and joint boxes (651.2)

Location

Ground floor

Description

Sample supporting photograph